

CITY OF SPRINGFIELD
INTER-OFFICE MEMORANDUM

ATTENTION OF _____

DATE OCT. 17, 1977

DEPARTMENT _____

MENO TO FILE.

RE: Ozark Fire Extinguisher, 1721 E. Division.

An inspection of Ozark Fire Extinguisher was made today to see if they had eliminated their discharge to the North Branch of Jordan Creek. It appears that the problem has been corrected since they have removed all of the pipes that came out of the North side of their building. Periodic inspection of the area will be made to assure that no other problem occurs.

1721 E. DIVISION

SIGNED

Gene Rabst

September 22, 1977

Mr. Kent Lawson
Ozark Fire Extinguisher & Equipment Company
1721 East Division Street
Springfield, Missouri 65803

Dear Mr. Lawson:

On a routine inspection of the north branch of Jordan Creek, personnel from this office observed three separate discharges from your building at 1721 East Division. Upon investigation it was found that two of the discharges are from the sink drain that is adjacent to the north wall of your building. The third discharge is from a hole that was knocked through the wall to act as a floor drain. Please be advised that these discharges are in violation of City, State, and Federal Water Pollution Control Laws. Steps should be taken to eliminate these discharges by placing them into the sanitary sewer. The Department of Building Regulations, in City Hall should be contacted to determine what permits are necessary to implement the required changes.

If you need further assistance or have any questions, please do not hesitate to call.

Yours truly,

Eugene Pabst
Water Pollution Control Inspector III
Surveillance & Enforcement

EP:pg

cc: Mr. John Nixon, Regional Administrator, Department of Natural Resources
Mr. Dick Nichols, Director of Building Regulations
Public Works File

1721 E. Division